

# **ZyXEL NWD-370N Multilingual Version**

## **Release 1.0.0**

## **Release Note**

**Date:** November.03, 2006

### **Supported Platforms:**

Windows 2000, Windows XP

### **Driver version:**

08/28/2006,6.0.1.75

### **Known issue:**

1. Unable to change transfer rate.
2. TKIP encryption is able to connect to AES encryption AP; AES encryption is able to connect to TKIP AP.
3. WPA/WPA-PSK encryption is able to connect to WPA2/WPA2-PSK AP; WPA2/WPA2-PSK encryption is able to connect to WPA/WPA-PSK AP.
4. Utilities that use Atheros solution can not exist in Windows at the same time.
5. 11n mode does not support WEP and TKIP.
6. 11n mode does not support Ad-Hoc.
7. Can not make connection with a double quotation mark in SSID.
8. Throughput can not up to 20Mbps at Ad-Hoc mode.
9. It sometimes take about 1~2 minutes to obtain IP when change WPA/WPA-PSK settings.
10. WHQL has not been passed.
11. Sometimes Windows cursor becomes slow in few systems.
12. Sometimes Windows blue screen when traffic in few system.
13. Lack of "Channel Width" and "PEAP inner EAP also support "GTC" on-line help.

### **Notes:**

1. No AP Mode.

### **Features:**

**Modification in 1.0.0 | 11/03/2006**

#### **1. Driver Changed.**

N/A

#### **2. Utility Changed.**

2.1 Formal release.

**Modification in 1.0.0b5 | 10/12/2006**

#### **1. Driver Changed.**

1.1 Change to v6.0.1.75

1.2 [BUG\_FIXED]Power saving mode is unavailable.

**2. Utility Changed.**

- 2.1 [BUG\_FIXED]Show 802.11g when connect at 11b mode.
- 2.2 Include multilingual web helps.
- 2.3 Add channel width info in link info page.
- 2.4 Rename "place" to "time" in site survey page in TC version.

**Modification in 1.0.0b4 | 09/04/2006**

**1. Driver Changed.**

N/A

**2. Utility Changed.**

- 2.1 [BUG\_FIXED]The detection of WPA/WPA-PSK failed in site survey page.
- 2.2 Authentication shows "Open" when security setting is WPA-PSK.

**Modification in 1.0.0b3 | 08/07/2006**

**1. Driver Changed.**

N/A

**2. Utility Changed.**

- 2.1 Change utility background.

**Modification in 1.0.0b2 | 07/28/2006**

**1. Driver Changed.**

N/A

**2. Utility Changed.**

- 2.1 [BUG\_FIXED]ACS service can not be started.
- 2.2 [BUG\_FIXED]Channel list in Ad-Hoc setting page is blank.

**Modification in 1.0.0b1 | 07/20/2006**

**1. Driver Changed.**

N/A

**2. Utility Changed.**

- 2.1 Multilingual version.