

ZyXEL G-162 CD Version Release 2.0 Release Note

Date: Dec. 27, 2004

Supported Platforms:

Window98 SE, Window ME, Windows 2000 and Windows XP

Known issue:

1.Driver issue.

- 1.0 In ASUS L3400 Note Book. The PC was often shut down with G162 utility.
- 1.1 Cannot change Tx Rate from 2Mbps to 1Mbps or 11Mbps to 2Mbps
- 1.2 Constant switching of WEP transmit key can lead to lose of connection.
- 1.3 Under Win98/ME, Power-Saving changes are not reflected in Advanced Driver page.
- 1.4 Odyssey SDK is left on the system after un-installation. To remove Odyssey SDK, you need to go to control panel and manually select “uninstall” for this program.
- 1.5 Odyssey Client should not be installed on the same system that has Odyssey SDK. It will cause both program to stop functioning.
- 1.6 Profile name disappeared when closed the utility and reopened the utility.
- 1.7 After install the utility. In some cases, the utility table can't appear.
- 1.8 In Ad-hoc mode the utility show wrong profile name.

Features:

Modification in 1.0.0 | 05/10/2004

- 1. Formal Release-
- 1.1 Support Wi-Fi WPA function
- 1.2 Pass Microsoft WHQL
- 1.3 Support 256-bit WEP Encryption
- 1.4 Support multilingual user interface

Modification in 2.0.0 | 012/25/2004

- 2.1 Add OTIST feature.
- 2.2 Add Russian version utility.
- 2.3 Fix 256-bit WEP Encryption problem.